



DO NOT WELD BOTTOM CHORD  
TO STABILIZER PLATE

JOIST TYPE

BOLTS NOT SUPPLIED BY CANAM

