


JOIST TYPE



BOLTS NOT SUPPLIED BY CANAM

* COLUMN ELEVATION MUST BE SMALLER THAN ANGLE ELEVATION