



DO NOT WELD BOTTOM CHORD  
TO STABILIZER PLATE

JOIST TYPE  
 BOLTS NOT SUPPLIED BY CANAM

