



DO NOT WELD BOTTOM CHORD  
TO STABILIZER PLATE

GIRDER TYPE 

BOLTS NOT SUPPLIED BY CANAM