



DO NOT WELD BOTTOM CHORD TO STABILIZER PLATE

JOIST TYPE

BOLTS NOT SUPPLIED BY CANAM

