



DO NOT WELD BOTTOM CHORD  
TO STABILIZER PLATE

GIRDER TYPE **22W**  
 BOLTS NOT SUPPLIED BY CANAM